

BRIDGE INVENTORY LIST

GRANT COUNTY

Str No	Owner	Custodian	Main Material	Main Design	Length (meters)	Length (ft)	Width (meters)	Width (ft)	Year Built	year recon	Open/Posted/Closed (41)	posting	suff rate	location	sub rating	sup rating	culv rating	scour crit	adt total	fcins preq	bypass len	dk rating	deficiency
26011040	2 County Hwy Agency		Continuous	01 Slab	10.972	36.0	8.138	26.7	1948	-1	A Open, no restriction	5	78.8	14.6W & 0.5N MARVIN	5	7	N	U	95	N	3.218694	7	
26018060	2 County Hwy Agency		1 Concrete	02 Stringer/Girder	9.753	32.0	6.706	22.0	1930	-1	P Posted for load	2	48.7	13.9W & 1.5S MARVIN	4	5	N	U	52	N	3.218694	5	S
26019100	2 County Hwy Agency		Continuous	01 Slab	16.367	53.7	8.138	26.7	1948	-1	A Open, no restriction	5	88.8	13.8W & 5.5S MARVIN	6	6	N	8	52	N	3.218694	5	
26022120	2 County Hwy Agency		Continuous	19 Culvert	7.498	24.6	0	0.0	1992	-1	A Open, no restriction	5	89.0	3N & 12.8W S SHORE	N	N	5	8	52	N	3.218694	N	
26023120	2 County Hwy Agency		Concrete	04 Tee Beam	24.749	81.2	10.516	34.5	1992	-1	A Open, no restriction	5	99.0	3N & 12.7W S SHORE	7	8	N	8	52	N	3.218694	7	
26026090	2 County Hwy Agency		7 Wood or Timber	02 Stringer/Girder	9.144	30.0	7.315	24.0	1958	1980	P Posted for load	0	49.2	13.1W & 4.5S MARVIN	5	6	N	U	45	N	3.218694	6	S
26030032	2 County Hwy Agency		Concrete	04 Tee Beam	10.668	35.0	9.51	31.2	1996	-1	A Open, no restriction	5	97.0	12.5W & 1.5N MARVIN	7	8	N	U	25	N	3.218694	7	
26030067	2 County Hwy Agency		3 Steel	02 Stringer/Girder	8.839	29.0	7.315	24.0	1935	1962	P Posted for load	1	40.3	2S & 12.5W MARVIN	4	5	N	U	107	N	3.218694	6	S
26030087	2 County Hwy Agency		Concrete	04 Tee Beam	20.1677017	66.2	9.34730148	30.7	2004	-1	A Open, no restriction	5	98.0	12.5W & 4.0S MARVIN	7	8	N	8	25	N	3.218694	7	
26030103	2 County Hwy Agency		Concrete	04 Tee Beam	18.6802788	61.3	9.348216	30.7	2004	-1	A Open, no restriction	5	98.0	6.0S & 12.5W MARVIN	7	7	N	8	12	N	3.218694	7	
26031030	2 County Hwy Agency		Concrete	04 Tee Beam	17.1197014	56.2	8.2296	27.0	2008	-1	A Open, no restriction	5	100.0	12.6W & 1.5N MARVIN	7	8	N	8	35	N	3.218694	7	
26032070	2 County Hwy Agency		1 Concrete	22 Channel Beam	24.688	81.0	9.754	32.0	1970	-1	A Open, no restriction	5	78.8	2.5S & 12.2W MARVIN	5	5	N	8	107	N	3.218694	6	
26032080	2 County Hwy Agency		Concrete	04 Tee Beam	17.1197014	56.2	8.2296	27.0	2010	-1	A Open, no restriction	5	100.0	12.5W & 3.5S MARVIN	7	8	N	8	52	N	3.218694	7	
26035100	2 County Hwy Agency		3 Steel	02 Stringer/Girder	26.212	86.0	6.858	22.5	1932	-1	B Posting Recommended	5	61.4	12.2W & 5.5S MARVIN	5	5	N	8	52	N	3.218694	5	
26040027	2 County Hwy Agency		3 Steel	02 Stringer/Girder	10.363	34.0	7.315	24.0	1936	1965	P Posted for load	0	48.2	11.7W & 1.8N MARVIN	6	5	N	U	25	N	3.218694	6	S
26050024	2 County Hwy Agency		Concrete	02 Stringer/Girder	8.229	27.0	6.919	22.7	2000	-1	A Open, no restriction	5	99.0	10.7W & 2.1N MARVIN	7	8	N	U	25	N	3.218694	7	
26050088	2 County Hwy Agency		3 Steel	02 Stringer/Girder	24.384	80.0	5.944	19.5	1936	-1	P Posted for load	0	47.0	10.7W & 4.3S MARVIN	4	4	N	U	20	N	3.218694	6	S
26055040	2 County Hwy Agency		Continuous	19 Culvert	9.906	32.5	9.053	29.7	1931	-1	A Open, no restriction	5	89.8	10.2W & 0.5N MARVIN	N	N	7	8	52	N	3.218694	N	
26056020	2 County Hwy Agency		1 Concrete	22 Channel Beam	7.62	25.0	7.772	25.5	1956	-1	P Posted for load	2	65.0	10.1W & 2.5N MARVIN	5	5	N	U	52	N	3.218694	7	
26060084	2 County Hwy Agency		Continuous	19 Culvert	7.559	24.8	0	0.0	1939	-1	A Open, no restriction	5	89.4	3.6N CODINGTON LINE	N	N	7	8	2388	N	3.218694	N	
26060089	2 County Hwy Agency		Continuous	19 Culvert	6.339	20.8	0	0.0	1940	-1	A Open, no restriction	5	81.3	3.1N CODINGTON LINE	N	N	5	8	2500	N	3.218694	N	
26070081	2 County Hwy Agency		7 Wood or Timber	02 Stringer/Girder	7.55904	24.8	7.62	25.0	1960	-1	A Open, no restriction	5	75.2	3.1 MI S & 8 W OF MARVIN	5	5	N	U	35	N	3.218688	6	
26090071	2 County Hwy Agency		Continuous	19 Culvert	6.797	22.3	8.992	29.5	1936	1980	A Open, no restriction	5	89.8	6.7W & 2.6S MARVIN	N	N	6	8	35	N	6.437388	N	
26155047	2 County Hwy Agency		3 Steel	02 Stringer/Girder	87.477	286.9	8.23	27.0	1940	-1	A Open, no restriction	5	86.4	MAIN STREET MARVIN	6	6	N	N	125	N	1.609347	6	
26169010	2 County Hwy Agency		Continuous	19 Culvert	6.4	21.0	0	0.0	1941	-1	A Open, no restriction	5	89.7	1.2E & 3.5N MARVIN	N	N	7	8	130	N	9.656082	N	
26170008	2 County Hwy Agency		7 Wood or Timber	02 Stringer/Girder	11.76528	38.6	7.40664	24.3	1930	1985	P Posted for load	0	47.5	1.3E & 3.7N MARVIN	6	5	N	U	54	N	3.218694	6	S
26190004	2 County Hwy Agency		3 Steel	19 Culvert	12.4968	41.0	0	0.0	2009	-1	A Open, no restriction	5	100.0	3.3E & 4.1N MARVIN	N	N	7	8	20	N	3.218694	N	
26190016	2 County Hwy Agency		3 Steel	19 Culvert	7.9248	26.0	0	0.0	2009	-1	A Open, no restriction	5	100.0	3.3E & 2.9N MARVIN	N	N	7	8	25	N	3.218694	N	
26199000	2 County Hwy Agency		7 Wood or Timber	02 Stringer/Girder	7.406	24.3	7.315	24.0	1958	-1	P Posted for load	1	42.0	4.2E & 4.5N MARVIN	4	6	N	U	52	N	3.218694	6	S
26200011	2 County Hwy Agency		Concrete	04 Tee Beam	10.88136	35.7	8.26008	27.1	2012	-1	A Open, no restriction	5	100.0	4.3E & 3.4N MARVIN	7	8	N	U	25	N	3.218694	7	
26200043	2 County Hwy Agency		3 Steel	02 Stringer/Girder	9.448	31.0	7.346	24.1	1930	1965	P Posted for load	1	52.7	4.3E & 0.2N MARVIN	5	5	N	U	25	N	3.218694	7	
26201010	2 County Hwy Agency		Concrete	02 Stringer/Girder	10.668	35.0	9.479	31.1	1998	-1	A Open, no restriction	5	97.0	3.5N & 4.5E MARVIN	6	8	N	U	52	N	3.218694	7	
26205100	2 County Hwy Agency		Continuous	19 Culvert	7.924	26.0	9.754	32.0	1930	1970	A Open, no restriction	5	89.8	4.8E & 5.5S MARVIN	N	N	7	8	52	N	3.218694	N	
26210006	2 County Hwy Agency		Continuous	19 Culvert	8.737701	28.7	0	0.0	2005	-1	A Open, no restriction	5	100.0	5.5E & 4.0N MARVIN	N	N	8	8	25	N	4.828032	N	
26210043	2 County Hwy Agency		1 Concrete	19 Culvert	7.784	25.5	0	0.0	2001	-1	A Open, no restriction	5	100.0	5.3E & 0.2N MARVIN	N	N	8	8	95	N	3.218694	N	
26210071	2 County Hwy Agency		3 Steel	02 Stringer/Girder	8.229	27.0	5.639	18.5	1925	1955	P Posted for load	0	35.7	5.3E & 2.6S MARVIN	5	5	N	U	35	N	3.218694	6	S
26215000	2 County Hwy Agency		Concrete	04 Tee Beam	7.52856	24.7	8.26008	27.1	2007	-1	A Open, no restriction	5	100.0	5.8E & 4.5N MARVIN	7	8	N	U	35	N	3.218694	7	
26220049	2 County Hwy Agency		7 Wood or Timber	02 Stringer/Girder	10.363	34.0	7.346	24.1	1926	1965	P Posted for load	0	57.5	7W & 2.1N MILBANK	6	6	N	U	25	N	3.218694	6	S
26220070	2 County Hwy Agency		Continuous	19 Culvert	6.29930162	20.7	0	0.0	2008	-1	A Open, no restriction	5	100.0	0.5 MI N. OF TWIN BROOKS	N	N	8	8	100	N	3.218688	N	
26221050	2 County Hwy Agency		Continuous	01 Slab	15.849	52.0	6.218	20.4	1926	-1	A Open, no restriction	5	76.8	6.9W & 2N MILBANK	5	6	N	U	100	N	3.218694	6	
26225050	2 County Hwy Agency		Continuous	01 Slab	15.849	52.0	5.852	19.2	1926	-1	P Posted for load	2	70.0	6.5W & 2N MILBANK	6	6	N	U	100	N	3.218694	5	F
26230048	2 County Hwy Agency		1 Concrete	22 Channel Beam	10.972	36.0	9.754	32.0	1961	-1	A Open, no restriction	5	48.6	1E & 3.2N TWIN BROOKS	3	5	N	U	332	N	3.218694	7	S
26230068	2 County Hwy Agency		Concrete	04 Tee Beam	12.192	40.0	9.418	30.9	1973	-1	A Open, no restriction	5	89.7	1E & 1.2N TWIN BROOKS	6	8	N	U	341	N	3.218694	7	
26230091	2 County Hwy Agency		Concrete	04 Tee Beam	7.83336	25.7	10.60704	34.8	2006	-1	A Open, no restriction	5	99.9	6W & 2.1S MILBANK	7	8	N	U	341	N	3.218688	7	
26230106	2 County Hwy Agency		Continuous	19 Culvert	6.858	22.5	0	0.0	1950	1964	A Open, no restriction	5	92.7	3.5S US 12	N	N	6	8	445	N	3.218694	N	
26230116	2 County Hwy Agency		3 Steel	02 Stringer/Girder	9.753	32.0	9.235	30.3	1930	1964	P Posted for load	1	48.7	3.4N SD 20	6	5	N	U	486	N	3.218694	7	S
26230218	2 County Hwy Agency		Continuous	19 Culvert	6.299	20.7	0	0.0	2000	-1	A Open, no restriction	5	100.0	6.8S SD 20	N	N	8	8	184	N	3.218694	N	
26232100	2 County Hwy Agency		Concrete	04 Tee Beam	10.88136	35.7	8.26008	27.1	2005	-1	A Open, no restriction	5	100.0	4.8W & 3.0S MILBANK	7	8	N	U	35	N	3.218694	7	
26240068	2 County Hwy Agency		7 Wood or Timber	02 Stringer/Girder	10.668	35.0	7.407	24.3	1942	1965	P Posted for load	0	53.5	5W & 0.2N MILBANK	6	6	N	U	25	N	3.218694	6	S
26240091	2 County Hwy Agency		Concrete	04 Tee Beam	10.88136	35.7	8.26008	27.1	2007	-1	A Open, no restriction	5	100.0	5W & 2.1S MILBANK	7	8	N	U	20	N	3.218694	7	
26240120	2 County Hwy Agency		Concrete	04 Tee Beam	10.88136	35.7	8.26008	27.1	2012	-1	A Open, no restriction	5	100.0	5W & 5S MILBANK	7	8	N	U	25	N	3.218694	7	
26240191	2 County Hwy Agency		7 Wood or Timber	02 Stringer/Girder	10.363	34.0	6.187	20.3	1936	1970	P Posted for load	0	57.5	1E & 0.1S STRANDBURG	6	6	N	U	25	N	3.218694	6	S
26243190	2 County Hwy Agency		Continuous	19 Culvert	6.3	20.7	0	0.0	2000	-1	A Open, no restriction	5	99.9	0.3N & 1.3E STRANDBURG	N	N	8	8	250	N	6.437388	N	
26245140	2 County Hwy Agency		7 Wood or Timber	01 Slab	7.3152	24.0	7.40664	24.3	1901	-1	A Open, no restriction	5	88.8	2.5E & 6.0S TWIN BROOKS	6	6	N	U	35	N	3.218688	6	
26246090	2 County Hwy Agency		Concrete	04 Tee Beam	10.8204	35.5	9.4488	31.0	2003	-1	A Open, no restriction	5	100.0	2.6E & 1.0S TWIN BROOKS	7	8	N	U	52	N	4.828032	7	
26249010	2 County Hwy Agency		Concrete	04 Tee Beam	10.85088	35.6	9.41832	30.9	2001	-1	A Open, no restriction	5	100.0	6N & 4W MILBANK	7	8	N	U	52	N	3.218694	7	

